



















	INSPECTION REPORT	Client	“Aspect-31”LLC	Conclusion
		Inspector	Mr Peter Zhang	
		Supplier	LINYI ZHENGDA WOOD CO.,LTD	Page 1 of 2

1. General Information

 2013.10.9 07:23			 8.28.2013 02:36
Linyi zhengda wood	poplar core drying	Zheng da wood Factory	Veneer graded and selected
		 2013.12.14 11:16	 2013.6.29 22:29
Plywood cold-pressing	Plywood hot-pressing	Jointing Poplar Veneer	Plywood Sanding
		 7.25.2013 05:46	
Joint veneer	Check quality	Plywood grading	Check thickness
			 2014.3.20 17:00
Carton package	Plywood package	Loading container	Edge sealed Brown paint
			
Dark brown film faced plywood	Wiremesh film faced plywood	Antislip film faced plywood	Black film faced plywood